

63-67 Front Repair Panels

These repair panels are used when the top surround panel is not being replaced.

- A** LH Top Fender Panel MM 2O/S 8200363 369.50
- B** RH Top Fender Panel MM 2O/S 8200364 369.50
- C** Center Nose Panel MM O/S 8200365 199.95
- Center Wiper Panel MM O/S 8200366 127.50
- D** Door to Door Wiper Panel MM O/S 8200367 224.50
- Head Lamp Header Bar Parts:
- E** Steel Reinforcement Beam O/S 8200312 105.00
- Supports the head lamp end plates
- Steel Beam with Bonding Strip O/S 8200320 199.75
- Bonds to top surround panel. MM
- F** Header Bonding Strip Only MM O/S 8200321 86.50
- Head Lamp Steel End Plates:
- LH Outer Steel End Plate 8200316 30.00
- LH Inner Steel End Plate 8200317 30.00
- RH Outer Steel End Plate 8200318 30.00
- RH Inner Steel End Plate 8200319 39.95

- Head Lamp End Plate Bonding Strips:
- LH Outer End Plate B/S MM 8200322 29.90
- LH Inner End Plate B/S MM 8200323 29.90
- RH Outer End Plate B/S MM 8200324 29.90
- RH Inner End Plate B/S MM 8200325 29.90

Key LH= Left drivers side RH = Right side
 B/S = Bonding Strip
 MM = Match Molded, smooth both sides
 HL = Hand Laid fiberglass smooth 1 side
 * = Shipped by Truck, freight collect
 O/S = Oversize 2O/S = Double Oversize


Note: These panels are available in colors
 63-64 White - 65-66 Gray - 67 Black

63-67 Inner Fender Skirts

63 LH Inner Skirt O/S MM	8200422	329.95
63 RH Inner Skirt O/S MM	8200423	329.95
64 LH Inner Skirt O/S MM	8200426	329.95
64 RH Inner Skirt O/S MM	8200427	329.95
65 LH Inner Skirt O/S MM	8200372	329.95
65 RH Inner Skirt O/S MM	8200375	329.95
66-67 LH Inner Skirt O/S MM	8200373	329.95
66-67 RH Inner Skirt O/S MM	8200376	329.95
63-67 LH Inner Skirt O/S HL	8200374	269.00
66-67 RH Inner Skirt O/S HL	8200377	269.00
63-67 LH Inner Skirt Battery Access Panel Only with AC or 65 396 Only MM	2333120	89.00
Panel With T-Nuts Installed MM	2333128	129.00

63 Upper Skirt to Top Surround Bonding Strip 4 Piece Set
 MM Available separately below 8200370 172.50

Front B/S LH	8200394	RH	8200395	44.50
Rear B/S LH	8200396	RH	8200397	44.50



Y 63-67 Fender Tip Set replaces the pieces removed when Side Exhaust was Installed. Includes Front & Rear Tips, For LH & RH Sides. MM 8200368 179.95

Front Tip LH	8200452	RH	8200453	47.50
Rear Tip LH	8200454	RH	8200455	47.50

63-67 Front Fiberglass

- 63-67 Top Surround Panels Truck Ship *
- GM Replacement Panel MM 8200301 775.00
- K** Reproduction Panel MM 8200302 1079.95
- KEF** Panel with Header Bar & B/S 8200371 1395.00
- L** 63 Head Lamp Housing Outer Skin Only:
- HL LH 8200314 79.50 RH 8200315 79.50
- M** 63 Hood Wedge Fender Supports Bonding Strips
- MM LH 8200309 44.50 RH 8200310 44.50
- Front Fender Louver Panels: All are MM UPS O/S
- Select from two different brands of MM Fiberglass.
- N** 63-64 Image LH 8200116 RH 8200117 239.50
- N** 63-64 Sermer LH 8200326 RH 8200327 274.50
- O** 65-66 Image LH 8200089 RH 8200090 239.50
- O** 65-66 Sermer LH 8200328 RH 8200329 294.50
- P** 67 Image LH 8200091 RH 8200092 239.50
- P** 67 Sermer LH 8200330 RH 8200331 299.50
- Q** 63-67 Top Surround to Side Fender Panel Bonding Strips
- These have the authentic reliefs and notches.
- MM LH 8200334 84.50 RH 8200335 84.50
- R** Corner Nose Parking Lamp Panel: all are MM O/S
- Specify year & allow the following approximate delivery.
- 63-64 2 weeks LH 8200338 RH 8200339 172.50
- 63-64 8 weeks LH 8200682 RH 8200683 204.00
- 65-67 2 weeks LH 8200340 RH 8200341 172.50
- 65-67 8 weeks LH 8200684 RH 8200685 204.00
- S** 63-67 Wheel Well Lip to Parking Lamp Panel Bond Strip
- MM LH 8200342 69.50 RH 8200343 69.50
- T** 63-67 Center Upper Grill Panel Between the Head Lamps MM O/S 8200346 109.95
- U** 63-67 Center Upper Grill Bonding Strip to the Top Surround Panel MM 8200347 59.50
- Center Lower Valance Panel Below Grill
- V** 63-64 Center Lower Panel MM O/S 8200349 132.00
- W** 65-67 Center Lower Panel MM O/S 8200350 132.00
- X** 63-67 Lower Grill to Parking Lamp Bonding Strip
- These small bonding strips are discontinued genuine GM.
- MM LH 8200351 24.50 RH 8200352 24.50

Truck Ship Prices Include the Crating Fee

