



AA	53-62 Sector Shaft Gear Lash Adjuster Screw	6800118	12.50
BB	53-62 Gear Lash Adjuster Shim 4 Piece Kit	6800114	22.50
CC	53-62 Adjuster Lock Nut	6800112	5.75
DD	53-62 Steering Box Side Cover Mounting Bolt 4 Piece Set	6800108	3.00
EE	53-62 Steering Box to Frame 9 Piece Mounting Kit with 3 bolts, 3 nuts & 3 lock washers.	6800106	9.50
FF	53-62 Steering Box To Frame Mounting Shim 6 Piece Set	6800107	3.60
GG	58-62 Steering Column Firewall Plate Stamped steel with Black finish.	6518101	4.50
HH	58-62 Steering Column Outer Firewall Seal 1/16" thick Black sponge.	6518102	4.50
II	53-62 Steering Column Inner Firewall Seal 5/8" thick Black sponge.	6518103	4.00
JJ	53-62 Steering Column Mounting Bracket 2 Piece Cushion Set Authentic profile extruded firm rubber, even has the No Skid 4 Raised Ribs on the inner surface as factory. Helps isolate road vibration from the column.	6518153	6.00

53-62 Upper Steering Column

Parts Not Identified Are Not Available

53-55 Horn Button Cap	2820102	68.00
A 56-57 and 59-62 Horn Button Cap	2820103	39.75
B 58 Horn Button Cap	2820104	39.75
C 56-62 Horn Contact mounts the cap	2819104	40.00
D 56-62 Mounting Screw 3 Piece Set	2819003	2.00
E 56-62 Steering Wheel less Hub & Bell		385.00
56-57 Red	6518160	56-57 Beige 6518161
59-60 Blue	6518165	58 Red 6518162
59-60 Turquoise	6518166	59-62 Black 6518163
61-62 Fawn Beige	6518168	59-62 Red 6518164
61 Jewel Blue	6518167	
F 56-62 Hub & Bell with Mounting rivets	6518156	129.00
G Wheel Mounting Screw 6 Piece Set	6518094	2.95
H 53-62 Wheel Mounting Nut	6518090	3.00
I 53-62 Wheel Mounting Washer	6518092	7.75
J Directional Housing Die Cast Zinc Excellent Used factory. Empty - No internal parts included. Bare housing only.	6521490	0.00
K 56-66 Steering Column Wedge with Mounting Screw This tapered block tightens the directional signal housing to the column jacket.	6518095	11.50
L 55-62 Horn Contact Brush	2819101	20.00
M 55-62 Directional Switch NOS	2895101	125.00
M 55-62 Directional Switch Repr	2895152	29.50
N 53-62 Steering Column Upper Bearing with Horn Wire Repr Bearing with horn wire	6521196	24.00
NOS Bearing with horn wire	6521101	69.00
O 53-62 Upper Bearing Spring	6521100	4.00
P 58-62 Cast Aluminum Steering Column Lower Cover below Gauge Cluster, paint as reqd	6518104	29.95

53-62 Steering Box

Parts Not Identified Are Not Available

Q 53-62 Steering Box Side Cover Gasket Authentic die cut tan fiber.	6521099	3.50
R 53-62 Sector Shaft Oil Seal	6521202	9.50
S 53-62 Sector Inner Bearing	6521204	13.75
T 53-62 Sector Roller Ball Bearing 22 Piece Set	6521206	7.50
U 53-62 Sector Outer Bearing	6521208	12.50
V 53-62 Worm Gear Upper or Lower Bearing 2 Reqd	6521210	17.25
W 53-62 Worm Gear Upper or Lower Bearing Race 2 reqd	6521212	13.50

53-62 Steering Box Bearing Race & Seal Minor Kit

Includes 29 Pieces: 2 Worm Gear Bearings, 2 Worm Gear Races, 1 Sector Oil Seal, 1 Sector Shaft Inner Bearing, 1 Sector Shaft Outer Bearing, 22 Sector Gear Ball Bearings and Side Cover Gasket. Includes Items **Q+R+S+T+U+V+W** 6521102 74.85

X 53-62 Steering Box Worm Gear without Bearings or Races	6521214	375.00
Y 53-62 Sector Shaft Roller Wheel with Ball Bearings this Chromium Molybdenum Steel Roller is heat treated to Rockwell hardness # 58 & includes 22 bearings. Sector Shaft Not Included	6521216	200.00
Z 53-62 Sector Race 2 reqd.	6521218	31.25

53-62 Steering Box Major Rebuild Kit

Steering Box Rebuild Kit Includes
 1 New Worm Gear with Shaft & Nut,
 2 New Worm Gear Caged Bearing & Races
 2 New Worm Gear Races,
 1 New Sector Roller Wheel Only,
 22 New Sector Shaft Ball Bearing & Races
 2 New Sector Shaft Bearings & 1 Oil Seal,
 1 New Upper Bearing with horn wire,
 1 New Side Cover Gasket,
53-57 Steering Box Service 6518705 439.95
58-62 Steering Box Service 6518710 439.95

53-82 Steering Box Lube

Steering Box Lube very thick, install with a grease or caulking gun. 14 ounces 8800446 6.50

63-66 Steering Column Mast Jacket Clamp

Stamped steel with Black paint finish, includes indented hex head sheet metal mounting screw. 6518205 6.50
63-66 Indented Hex Washer Head Mounting Screw this is included with the above clamp 6518206 1.95

