
## Dr REBUILD Credit Card ORDERING ONLY on (800) 8669 DOC 155



700	CC 53-62 Adjuster Lock Nut	6800112	5.75			
	DD 53-62 Steering Box Side Cover Mou					
	4 Piece Set	6800108	3.00			
	EE 53-62 Steering Box to Frame 9 Piece	ce Mounting K	(it			
$\Sigma I / I$	with 3 bolts, 3 nuts & 3 lock washers.	6800106	9.50			
	FF 53-62 Steering Box To Frame Mounting Shim					
// )	6 Piece Set	6800107	3.60			
]	// GG 58-62 Steering Column Firewall Plate					
	Stamped steel with Black finish.	6518101	4.50			
	HH 58-62 Steering Column Outer Firewall Seal					
N	1/16" thick Black sponge.	6518102	4.50			
)"\	II 53-62 Steering Column Inner Firewall Seal					
<del>∠</del> ~	5/8" thick Black sponge.	6518103	4.00			
_	JJ53-62 Steering Column Mounting Bra	cket 2 Piece				
÷	Cushion Set Authentic profile extruded firm rubber,					
/	even has the No Skid 4 Raised Ri					
	inner surface as factory. Helps isola	ate road				
	vibration from the column.	6518153	6.00			

53-62 Sector Shaft Gear Lash

53-62 Gear Lash Adjuster Shim

Adjuster Screw

4 Piece Kt

BB

### **53-62 Upper Steering Column**

## Parts Not Identified Are Not Available Pa

53-55 Horn Button	Сар		282010	)2	68.00
A 56-57 and 59-62 H	lorn Button C	ар	282010	)3	39.75
B 58 Horn Button Cap			282010	)4	39.75
C 56-62 Horn Conta	ct mounts the	е сар	281910	)4	40.00
D 56-62 Mounting Sc	crew 3 Piece	Set	281900	)3	2.00
E 56-62 Steering Wh	neel less Hul	& Bell		3	385.00
56-57 <b>Red</b>	6518160	56-57	Beige	65	18161
59-60 Blue	6518165	58 <b>Re</b>	d	65	18162
59-60 Turquoise	6518166	59-62	Black	65	18163
61-62 Fawn Beige	6518168	59-62	Red	65	18164
61 Jewel Blue	6518167				
F 56-62 Hub & Bell w	ith Mounting r	ivets	651815	6 1	129.00
G Wheel Mounting S	crow 6 Diace	Sot	651800	1/1	2 05

6	1 <b>Jewel Blue</b> 6518167				
F	56-62 <b>Hub &amp; Bell</b> with Mounting rivets	6518156	129.00		
G	Wheel Mounting Screw 6 Piece Set	6518094	2.95		
Н	53-62 Wheel Mounting Nut	6518090	3.00		
I	53-62 Wheel Mounting Washer	6518092	7.75		
J	J Directional Housing Die Cast Zinc				
Excellent Used factory Empty No internal parts					

Excellent Used factory. Empty - No internal parts included. Bare housing only. 6521490 0.00 K 56-66 Steering Column Wedge with Mounting Screw This tapered block tightens the directional signal housing to the column jacket. 6518095 11.50 L 55-62 Horn Contact Brush 2819101 20.00 M 55-62 Directional Switch NOS 2895101 125.00 M 55-62 Directional Switch Repro 2895152 29.50 N 53-62 Steering Column Upper Bearing with Horn Wire

O 53-62 Upper Bearing Spring 6521100 4.00
P 58-62 Cast Aluminum Steering Column Lower Cover below Gauge Cluster, paint as reqd 6518104 29.95

6521196 24.00

69.00

6521101

Repro Bearing with horn wire

NOS Bearing with horn wire

### 53-62 Steering Box

#### Parts Not Identified Are Not Available

Q 53-62 Steering Box Side Cover Gasket				
6521099	3.50			
6521202	9.50			
6521204	13.75			
g				
6521206	7.50			
6521208	12.50			
V 53-62 Worm Gear Upper or Lower Bearing				
6521210	17.25			
<b>W</b> 53-62 Worm Gear Upper or Lower Bearing Race				
6521212	13.50			
	6521099 6521202 6521204 <b>9</b> 6521206 6521208 rer <b>Bearing</b> 6521210 rer Bearing <b>Race</b>			

## 53-62 Steering Box Bearing Race & Seal Minor Kit

Includes 29 Pieces: 2 Worm Gear Bearings, 2 Worm Gear Races, 1 Sector Oil Seal, 1 Sector Shaft Inner Bearing, 1 Sector Shaft Outer Bearing, 22 Sector Gear Ball Bearings and Side Cover Gasket. Includes Items

Q+R+S+T+U+V+W 6521102 74.85

X 53-62 Steering Box Worm Gear without
 Bearings or Races 6521214 375.00
 Y 53-62 Sector Shaft Roller Wheel with Ball Bearings this

Chromium Molybdenum Steel Roller is heat treated to Rockwell hardness # 58 & includes 22 bearings.
Sector Shaft Not Included 6521216 200.00
Z 53-62 Sector Race 2 reqd. 6521218 31.25

# 53-62 Steering Box *Major* Rebuild Kit

### Steering Box Rebuild Kit Includes

- 1 New Worm Gear with Shaft & Nut,
- 2 New Worm Gear Caged Bearing & Races
- 2 New Worm Gear Races,
- 1 New Sector Roller Wheel Only,
- 22 New Sector Shaft Ball Bearing & Races
- 2 New Sector Shaft Bearings & 1 Oil Seal,
- 1 New Upper Bearing with horn wire,
- 1 New Side Cover Gasket,
- 53-57 Steering Box Service 58-62 Steering Box Service

6518705 **439.95** 6518710 **439.95** 

6800118 12.50

6800114 22.50

### 53-82 Steering Box Lube

Steering Box **Lube** very thick, install with a grease or caulking gun. 14 ounces 8800446 **6.50** 

### 63-66 Steering Column Mast Jacket Clamp

Stamped steel with Black paint finish, includes indented hex head sheet metal mounting screw. 6518205 6.50



63-66 Indented Hex Washer Head Mounting **Screw** this is included with the above clamp 6518206 **1.** 

1.95

