

**Coils  
Delco  
& Rebro**




**NOT RETURNABLE if Factory Seal Broken**

56-74 12 Volt Coil except Transistorized Ignition Delco but it is no longer made in the USA.	2170205	48.50
63-67 Coil Capacitor except T.I.		
Replacement for 56-62 and 68-74.	2170206	12.50
64-71 12 Volt Coil with T.I. replacement.	2170204	93.50
75-81 12 Volt Coil Delco	2170207	62.50
82, 84 1st design, 86 Volt Coil Delco	2170208	65.00
59-62 exc FI; Early 63; 64 365 375 HP Coil	2171091	79.00
Late 63; 64 250-300 HP Coil	2171087	79.00
65-67 327 except TI Coil	2171202	79.00
66 390 HP except TI Coil	2171232	79.00
67 390, 400 HP except TI Coil	2171264	79.00
68-74 427 or 454 except TI Coil	2171287	79.00
65-68 350, 375 HP with TI Coil	2171207	129.00
65 425 HP; Early 66 390 HP with TI Coil	2171210	129.00
Late 66 390 HP; 425, 450 HP with TI Coil	2171231	129.00
Late 66 390 HP; 425 HP with TI Coil	2171261	129.00
67-72 427 or 454 with TI Coil	2171263	129.00
68-71 327 or 350 with TI Coil	2171272	129.00
65-74 Coil Bracket Big Block except 3x2	2171288	17.25
65-74 Coil Bracket Big Block with 3x2	2171289	20.50


**Coil Resistor**

Identify these by the **Colored Dot** that is on the mount strap. Replacements Resistors **DO NOT** include a Colored Dot **NOR** look exactly like above.




55-62 all models and 63-64 F.I. Coil Resistor (Black Dot replacement)	9663601	14.25
63-67 exc F.I. Resistor (Blue Dot replm)	9663602	21.75
55-67 Resistor Mounting Screw	9663604	1.50

**Delco Distributor Caps**



53-55 6 Cylinder Distributor Cap Delco	2361103	14.50
<b>E</b> 55-57 V-8 Distributor Cap Delco	2361104	16.95
<b>F</b> 58-74 Distributor Cap Delco	2361105	21.10
58-62 Dual Point Cap Delco with two sliding doors for dual point adjustment Rebro	2361108	185.00
63-65 short F.I. Distributor Cap Delco	2361109	21.60
74-84 H.E.I. Distributor Cap Delco	2361110	23.75

**Distributor Parts**



<b>A</b> 62-74 Brass Coupling permits the tach cable to be screwed to the distributor.	9751140	18.00
<b>B</b> 62-74 Cross Shaft Gear USA	9751151	29.50
<b>B</b> 62-74 Cross Shaft Gear Imported	9751156	25.00
<b>C</b> 62-74 Cross Shaft Shim USA	9751153	4.50
<b>C</b> 62-74 Cross Shaft Shim Imported	9751107	3.00
<b>D</b> 62-74 Bronze Thrust Button	9751154	9.50
<b>ABCD</b> Coupling Gear Shim Button China	9751151	
62-74 Distributor Main Shafts:		
except Hi-Performance or T.I.	2361101	59.50
with Hi-Performance or T.I.	2361107	59.50
55-82 Lower Drive Gear NOS	2361102	45.00
55-82 Lower Gear Washer	2361203	7.70
58-74 Lubricator Kit NOS	2361204	45.00
55-82 Hold Down Clamp GM replacement	2364205	7.00
56-61 2x4 Oil Line, Wick & Cap	2364208	33.95


**Vacuum Advance Control**

The diaphragm in these dual pie-pan shaped units often leak after many years, and then vacuum advance is "kaput".

59-65 exc Hiper; 65 396; 66 390 T.I.; 68-69 350 T.I.; 68-69 435; 70-72 LT-1 Vacuum Advance Control	2410160	23.50
66 425; 67-69 390;		
69 350 HP exc T.I.; 70 350 & 454 Vacuum Advance Control	2410162	22.00
71-72 350 Vacuum Advance Control	2410164	18.50
71-72 454 exc LS-6 Vacuum Control	2410166	15.75
73-74 350 L-48 Vacuum Control	2410168	14.80
73-74 454 Vacuum Advance Control	2410170	12.45

**F.I. Distributor Spacer**

57-65 F.I. Distributor Mounting Spacer These are NOS discontinued Aluminum spacers necessary to mount the distributor. 7001219 60.00



**Distributor to Coil Wire**

53-54 Distributor to Coil Lead Wire	2394102	12.00
55-69 Distributor to Coil Lead Wire and Early 70 300-350 HP with distributor # 1111490 or 1111493	2394104	12.00
70-74 Distributor to Coil Lead Wire exc Early 70 300-350 HP with distributor # 111464, 1112020, 1112021, 1112050 or 1112051	2394106	12.00

**Points, Rotor, & Condenser**

**Breakerless Solid State Kit**

58-74 Electronic Ignition Conversion Kit replaces points without replacing the distributor, modifying the harness or even compromising the appearance. Every thing fit under the cap. Easy to do. 9751163 158.00

**Delco Distributor Points**

56-57 Points or		
56-61 Points with 2x4 Carb Delco	2384108	12.95
58-74 Points without 2x4 Carb Delco	2384110	18.50


**Delco Distributor Condenser**

53-57 Condenser or		
58-61 Condenser 2x4 Carb Delco	2393106	6.95
58-74 Condenser 1x4 Carb Delco	2393107	8.50

**Delco Distributor Rotor**

53-55 6 CYL Rotor Delco	2382105	10.00
55-57 8 CYL Rotor or		
58-61 2x4 Rotor Delco	2382107	8.35
58-74 Rotor except 2x4 Delco	2382108	7.35
74-91 H.E.I. Rotor Delco	2382109	9.00

**Distributor Gaskets**



Die Cut Distributor Mounting Gaskets		
<b>K</b> 55-74 Cork Mounting Gaskets Pair	7000119	3.50
<b>L</b> 75-82 Dense Fiber Gaskets Pair	2364206	2.80

**Complete Distributor**

Includes Rotor, Points, Condenser and Cap.		
57-61 Single Point #891	2361115	299.00
62-74 Distributor 250/300 HP	2361100	0.00
63-74 Distributor with HiPerformance	2361126	0.00
75-85 HEI Distributor	2361130	385.00

**Delco T.I. Amplifier**


**NOT RETURNABLE if Factory Seal Broken**

64-68 Delco Amplifier without pigtail	2383301	0.00
69-72 Delco Amplifier with pigtail	2383305	399.00
64-72 Rebro Amplifier Internal Module Only		
Updates & repairs burnt out amps	2383310	145.00

**T.I. = Transistorized Ignition**

**64-72 T.I. Amplifier Cover Gasket**

Replica die cut rubber like factory gaskets. Protects and prevents water damage to these expensive electronic parts. 2383000 6.50



**T.I. Wiring Harness**

Early 68 = Amplifier is without integral external harness		
Late 68 = Amplifier has an integral external harness		
64-Early 68 Auxillary Harness real GM discontinued, not a Rebro	2525123	176.00
64-65 Auxillary Harness similar colors	2525223	124.00
66-67 Auxillary Harness similar colors	2525224	124.00
Early 68 Auxillary Harness similar colors	2525124	125.00
Late 68-71 Auxillary Harness similar colors	2525230	126.50
64-Early 68 Auxillary Extension Harness	2525120	33.00
Late 68-71 Auxillary Extension Harness	2525122	50.00
68-71 Extension from Ignition Switch	2525232	17.00

**T.I. Harness Installation Kits**

Includes all the connectors, terminals and instructions that were used by the GM factory assembly line to install T.I.		
64-64 T.I. Installation Kit	2525160	10.00
66-67 T.I. Installation Kit	2525162	10.00
68-71 T.I. Installation Kit	2525164	10.00

**Assembly & Owners Manuals**

Reproductions of the Factory Manuals. These Assembly Instruction Manual are 8 1/2" by 11" with from 280 to 640 pages. Owners Manuals are an excellent info resource.

Assembly Manuals	Owners Manuals
56-57 9892056	20.75
58 9892058	20.75
59 9892059	20.75
60 9892060	20.75
61 9892061	20.75
62 9892062	20.75
63 9892063	20.75
64 9892064	20.75
65 9892065	20.75
66 9892066	20.75
67 9892067	20.75
68 9892068	20.75
69 9892069	20.75
70 9892070	20.75
71 9892071	20.75
72 9892072	20.75
73 9892073	20.75
74 9892074	20.75
75 9892075	20.75
76 9892076	20.75
77 9892077	20.75
78 9892078	20.75
79 9892079	20.75
80 9892080	20.75
81 9892081	20.75
82 9892082	20.75
58 9892158	11.75
59 9892159	11.75
60 9892160	11.75
61 9892161	11.75
62 9892162	11.75
63 9892163	11.75
64 9892164	11.75
65 9892165	11.75
66 9892166	11.75
67 9892167	11.75
68 9892168	11.75
69 9892169	11.75
70 9892170	11.75
71 9892171	11.75
72 9892172	11.75
73 9892173	11.75
74 9892174	11.75
75 9892175	11.75
76 9892176	11.75
77 9892177	11.75
78 9892178	11.75
79 9892179	11.75
80 9892180	11.75

**Hot Tip on 3 Ring Binders**

3 Ring Binders for these Assembly Manuals are available from other sources for \$ 5 to \$ 9.95 - but Staples™ or Office Depot™ are your best bet for these especially Hard To Find Rare Incredibly Specialized Corvette Parts.