




WARNING Leaking **Spark Control Hoses™** create havoc and are often characterized by one or more of these symptoms: Rough Idle, Flat Spots, Hard Starting, Poor Fuel Economy, Poor Acceleration Sputters and Knocking. Note: The diagrams supplied with these **Spark Control Hose Kits™** illustrate the relative position of the various parts that are connected. For the sake of clarity, some of these parts may be slightly shifted from their actual location to allow a clearer picture of the routing and connections. For this reason, some hoses may falsely appear to be Longer or Shorter than other hoses in these diagrams. DocRebuild made these kits from real Vettes. Then Zip copied our repro. Beware of Zip part numbers with a Z




- A Spark Control Hose 6 Piece Kit 3750347 12.00
- B New Spark Control Solenoid 3275608 69.50




- A Spark Control Hose 7 Piece Kit 3750348 12.00
- B New Spark Control Solenoid 3275610 69.50
- C Vacuum Tube Must Be Bent 3750328 10.00
- D Advance Tube Mounting Clip 2 reqd 3750420 5.50




- A Spark Control Hose 7 Piece Kit 3750350 13.00
- B New Spark Control Solenoid 3275616 69.50




- A Spark Control Hose 10 Piece Kit 3750351 16.00
- B New Spark Control Solenoid 3275618 69.50




- A Spark Control Hose 7 Piece Kit 3750352 14.00
- B New Spark Control Solenoid 3275612 69.50




- A Spark Control Hose 13 Piece Kit 3750353 18.00
- B Vacuum Tube Must Be Bent 3750328 10.00
- C Advance Tube Mounting Clip 2 reqd 3750420 5.50
- D New Spark Control Solenoid 3275620 0.00




- A Spark Control Hose 6 Piece Kit 3750358 14.00
- B New Spark Control Solenoid 3275612 69.50




- A Spark Control Hose 10 Piece Kit 3750359 17.00
- B Vacuum Tube Must Be Bent 3750328 10.00
- C Advance Tube Mounting Clip 2 Reqd 3750420 5.50
- D New Spark Control Solenoid 3275620 0.00




- A Spark Control Hose 6 Piece Kit 3750354 14.00
- B New Spark Control Solenoid 3275616 69.50



- A Spark Control Hose 7 Piece Kit 3750355 15.00
- B New Spark Control Solenoid 3275618 69.50



- A Spark Control Hose 5 Piece Kit 3750356 13.00
- B New Spark Control Solenoid 3275616 69.50



- A Spark Control Hose 6 Piece Kit 3750357 14.00
- B New Spark Control Solenoid 3275618 69.50