



**Water Pump Gaskets**




- A 65-74 Big Block Water Pump Gasket Set**  
 396-427-454 **3 Piece Cork** Gasket Set 1069580 5.00  
 396-427-454 **3 Piece Fiber** Gasket Set 1069574 4.00  
**Small Block Water Pump Gasket Sets**  
 55-62 **Cork 5 Piece Set 2B+C+2D** 1069548 5.00  
 55-62 **Fiber 5 Piece Set 2B+C+2D** 1069556 5.00  
 63-82 **Cork 3 Piece Set B+C+D** 1069551 5.00  
 63-82 **Fiber 3 Piece Set B+C+D** 1069558 4.00

**WATER PUMP FITTINGS**




- E 55-58 Straight Water Pump Fitting** or  
 63-82 **Intake Manifold Fitting** 8847110 8.00  
 55-58 **Curved Water Pump Fitting 5/8"** 8847112 16.45  
 59-62 **Curved Water Pump Fitting 3/4"** 8847114 16.45  
 61-62 **90 degree Water Pump Elbow** 1062104  
**F Water Pump Fittings** attaches the 3/4" hose  
 63-72 exc AC & 73-82 **Fitting** 1062306 11.25  
 63-72 with AC **Fitting** 1062308 9.45  
**G 65-74 Big Block Bypass Hose "Press In" Fitting** Use  
 one in the intake manifold & one in the water pump,  
 2 reqd **Repro** 1062212 8.00  
 2 reqd **NOS** 1062213 22.50

**Idler Pulley Water Pump Studs**



- H 58-62 Water Pump Mounting Stud**  
 Also mounts generator brace. 1062101 10.75  
**I 62-65 HiPer 327 Water Pump Mounting Stud**  
 Also mounts the idler pulley **NOS** 1062102 14.95


**Water Pump Bypass Hose**




- J 63-67 327 HiPerformance Bypass Hose**  
**Reproduction 327 hose.** 1062305 12.50  
**Replacement 327 hose.** 1062307 8.00  
**K 63-67 327 Bypass Hose Clamps** these are OEM,  
 not reproduction; 2 reqd 4166930 2.95  
 63-67 **Intake Fitting** 90 degree attaches the above hose  
 to the intake manifold. 1062103 19.50  
 63-67 **Slotted Intake manifold Fitting** 1062303 9.75  
**L 65-74 Big Block Bypass Pass Hose**  
**Reproduction Big Block Hose.** 1062215 15.75  
**Replacement Big Block Hose** 1062211 8.00  
 65-74 396 427 454 **OEM Bypass Hose Clamps 2 reqd.**  
**M 65-74 Side Screw design Clamp** 4166931 15.00  
**N Late 67 427 NOS Wittek Tower Clamp** 4166918 12.50

**Pulley Reinforcement**

- Water Pump Pulley Reinforcement  
 58-61 all 283; 67-68 300 HP  
 without AC; 66-68 427 with AC.  
**Repro USA** 1063422 4.95  
**OEM not repro** 1063092 6.75



**Water Pump Pulley**



- 55-Early 56 **Single Pulley #172** 1063430 119.50  
 Late 56-Early 58 **Single Pulley #974** 1063432 159.50  
 Late 58-62 **Single Pulley #815** 1063420 89.50  
 Late 58-62 **Single Pulley #815 with logo** 1063434 89.50  
 57-62 **Replacement Single Pulley** 1063114 90.00  
 62-68 340, 350, 360, 365, 375 HP  
**Double Pulley 7 1/8"** 1063109 0.00  
 63-65 250, 300 HP except AC Pulley  
 Replacement **Single 7 1/8"** 1063114 90.00  
 Reproduction **Double 7 1/8"** #356 1063436 189.00  
 66-68 300, 350 HP **Single 7 1/8"** 1063114 90.00  
 64-66 250, 300 HP with AC  
**Double Pulley** 1063110 169.00  
 64-65 365 HP AC **Double Pulley** 1063126 82.50  
 65-Early 67 396, 427 except AC  
**NOS Double #480** 1063440 169.50  
 66-68 350 HP AC exc PS **Double Pulley** 1063126 82.50  
 66-70 427/454 AC PS **Triple Pulley** 1063141 198.00  
 65-67 396/427 except AC **Double**  
 Reproduction **Double #656** 1063438 125.00  
**NOS Double #656** 1063118 127.00  
 68 327 300 HP except AC **Double #642** 1063122 97.50  
 Early 68 427 except AC or Auto **Double** 1063126 82.50  
 68-69 427 **Double #642** 1063122 97.50  
 68-69 L-88 **Double Pulley** 1063126 82.50  
 68-70 327 AC, 350 AC, **Double** 1063124 73.80  
 69-70 350, 370 HP exc AC **Double** 1063126 82.50  
 69-70 300 HP exc AC **Double** 1063122 97.50  
 71-79 350 except AC **Double Pulley** 1063135 145.00  
 71-75 Auxillary Front **Single Pulley** 1063138 65.00  
 71-73 454 All **Triple Pulley** 1063141 198.00  
 74 454 except AC **Triple Pulley** 1063141 198.00  
 75-77 350 with AC; 1063144 79.50  
 76-78 350 Calif. **Double Pulley** 1063135 145.00  
 78-79 350 with AC exc L-48 **Double** 1063144 79.50  
 79 L48 Calif. Auxillary Front **Single** 1063138 65.00  
 79-80 L82 **Double Pulley NOS** 1063135 145.00  
 80 L48; 81-82 All **Double Pulley** 1063144 79.50  
 80-82 Auxillary Front **Single Pulley** 1063138 65.00

**Harmonic Balancer**


- Harmonic balancers mount on the crankshaft.**  
 57-61 283; All GM there is a difference!  
 62-65 327 exc HiPer Balancer **GM** 1063250 71.00  
 62-68 327 HiPer; SpHiPer, FI Balancer  
 genuine GM replacement 1063252 149.00  
 66-67 327 exc HiPer Balancer **GM** 1063254 72.00  
 69-71 350 exc HiPer Balancer **GM** 1063258 136.65  
 69-82 350 HiPer Balancer **GM** 1063260 126.00  
 72-80 350 exc HiPer Balancer **GM** 1063262 149.75  
 65-69 369/427 HiPer Balancer **GM** 1063264 212.40  
 66-69 427 exc HiPer Balancer **GM** 1063266 350.00  
 67-69 L-88 Balancer **GM** 1063268 172.70  
 70-72 454 Balancer **GM** 1063270 234.00  
 73-74 454 Balancer **GM** 1063274 139.00

**Harmonic Balancer Mounting**

- 62-68 327 HiPer, SpHiPer, FI **Harmonic Balancer**  
**Mounting Key** genuine GM not repro 1063200 7.00  
 62-82 327/350 **Harmonic Balancer Mount Kit** cross drilled  
 grade 8 bolt & an internal lock washer 1063202 5.95  
 62-82 327/350 **Harmonic Balancer Mounting**  
**Special Thick Washer** 1063206 5.50  
 65-74 396/427/454 **Harmonic Balancer Mounting Kit**  
 grade 8 bolt with split lock washer 1063204 3.50  
 65-74 396/427/454 **Harmonic Balancer Mounting Kit**  
**Special Thick Washer** 1063208 6.75

**Idler Pulley & Bearing**

At last an inexpensive alternative to replacing your entire idler pulley, when only the bearing is worn. Use with 62-65 327 Hi Performance; 68-69 with AC 427 and 70-74 with AC 454.



- 62 340+360 HP **Idler Assy & Zinc Pulley** 1062199 123.50  
 63 340+360 HP **Idler Assy & Zinc Pulley** 1062203 107.50  
 64-65 Hiper **Idler Assy & Black Pulley** 1062204 107.50  
 Small Block **Idler Pulley Studs** are in the Far Left Column  
 68 427 AC **Idler Pulley Assembly** 1063426 135.00  
 69-74 427 or 454 with AC **Idler Pulley Assembly**  
**NOS Pulley Assembly** 1063132 200.00  
**Repro Pulley Assembly** 1063428 138.50  
 68-74 AC Big Block **Idler Pulley Stud** 1062200 19.50  
 68-74 Big Block **Idler Pulley Mount Hardware - no Stud:**  
 427/454 **AC with PS Mount Kit** 1062201 15.00  
 427/454 **AC without PS Mount Kit** 1062202 17.50

**Crankshaft Pulleys**

**Crank Pulleys mount on the Harmonic.**

- 55-57 with 1x4 **Single Pulley Replmnt** 1063220 85.00  
 56-Early 58 **Single Pulley #991** 1063442 136.50  
 Late 58-62 **Single Pulley #328** 1063446 154.50  
 62-63 340 360 #987 **Double Pulley** 1063448 0.00  
 62-63 340 360 **Replmnt Double Pulley** 1063224 52.50  
 63-65 250, 300 HP with PS **Double Pulley** 1063226 52.50  
 63-66 250, 300 HP exc AC **Double Pulley** 1063226 52.50  
 63-74 327 or 350 with PS exc 65-68 Sp Hiper  
**Single Pulley add on to front** 1063228 49.50  
 64-65 350 365 375HP #987 **Double Pulley** 1063448 0.00  
 64-65 350, 365, 375 HP **Replmnt Double** 1063224 52.50  
 64-67 327 with AC #838 **Double Pulley** 1063450 184.50  
 65-Early 69 396/427 to VIN 23, 995 approximately and  
 71 425 HP L-6 **Double Cast Iron** 1063230 166.75  
 66 350 HP with PS **Double Pulley** 1063226 52.50  
 66-67 300 HP exc AC **Single Pulley** 1063220 85.00  
 66-67 350 HP exc PS #987 **Double Pulley** 1063448 0.00  
 66-68 350 HP exc PS **Replmnt Double** 1063224 52.50  
 68 350 HP exc AC #987 **Double Pulley** 1063448 0.00  
 Early 68 300 HP exc AC **Double Pulley** 1063226 52.50  
 Early 68 327/350 with AC **Double Pulley** 1063450 184.50  
 Late 68-74 327 or 350 w/AC #013 **Double** 1063452 152.50  
 69-73 350 with HiPer, SpHiPer exc AC, HD or 4 speed  
**Double Pulley** 1063224 52.50  
 Late 69-74 427/454 exc L-88 after VIN 23, 995 approx  
 71 exc LS-6 **Double Stamped Steel** 1063232 54.00  
 74-80 350 exc AC **Double Pulley** 1063224 52.50  
 75-82 350 with AC **Double Pulley** 1063234 65.00  
 75-82 350 w/ PS **Single front add on Pulley** 1063236 52.00

**Crankshaft Pulley Mounting**

- 60-68 283/327 exc Sp Hiper **Crankshaft Pulley 3 Piece**  
**Mounting Kit with 3 grade 5 bolts** 1063210 7.00  
 62-82 327/350 **Crankshaft Pulley 6 Piece Mount Kit** with 3  
 grade 5 bolts & lock washers. Use with 8" dia. balancers  
 that are from 1 1/4" to 1 3/4" thick. 1063212 3.50  
 65-74 396/427/454 **Crankshaft Pulley 6 Piece Mounting Kit**  
 includes 3 grade 5 bolts with lock washers.  
 using a **Cast Iron Pulley** 1063214 3.50  
 using a **Stamped Steel Pulley** 1063216 3.50

**Harmonic Repair Kit**

- Repairs groove worn in balancer by the oil seal in the timing cover. Includes repair sleeve with sealant, timing cover gasket with oil seal, front lower oil pan seal with sealer plus complete installation instructions.  
**Small Block 265, 283, 327, 350 Select from...**  
 55-74 **Harmonic Sleeve Kit** 1063192 28.00  
 75-82 **Harmonic Sleeve Kit** 1063194 26.00  
**Big Block Harmonic Sleeve Kit** 1063196 29.50